

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 2

Sewershed: Gwynns Falls

Company: Savin

Date: 9/22/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW

Manhole_ID: S06I_007MH

Test ID: D1032-007009

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S06I_016MH
0			Water Level	
90.69999695			Dye Test Visible	DYE SEEN IN TAP
90.69999695	09		Tap Factory Active	
101.1999969	05		Hole	
141.3000031			Dye Test Visible	DYE SEEN IN TAP
141.3000031	09		Tap Factory Active	
146.3999939			Dye Test Visible	DYE SEEN AT JOINT
147.3999939	05		Crack Longitudinal	
147.3999939			Dye Test Visible	DYE SEEN IN CRACK

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 2
Sewershed: <u>Gwynns Falls</u>	Company: <u>Savin</u>	Date: <u>9/22/2009</u>
Test to be performed: Smoke <input type="checkbox"/> Dyed Water <input checked="" type="checkbox"/>	Ground Condition: Dry <input checked="" type="checkbox"/> Damp <input type="checkbox"/> Wet <input type="checkbox"/>	Supervisor: <u>JAW</u>
Manhole_ID: <u>S06I_007MH</u>	Test ID: <u>D1032-007009</u>	Notification Made: <u>NA</u> (Residents, Fire, 311)
149.6999969	Dye Test Visible	DYE SEEN AT JOINT
152.3999939	Dye Test Visible	DYE SEEN AT JOINT
155.8000031	Dye Test Visible	DYE SEEN AT JOINT
158.6999969	Dye Test Visible	DYE SEEN AT JOINT
185.6999969	Abandoned Survey	DYE IS COMPLETE